

Inspection Photo (s)
Specialty 43C
API # 05-045-14823
Inspection # 689303008



Location Photo #1



Location Photo #2

**Inspection Photo (s)
Specialty 43C
API # 05-045-14823
Inspection # 689303008**



Location Photo #3



Location Photo #4, Stained ground under scrubber pot, on 34A.

**Inspection Photo (s)
Specialty 43C
API # 05-045-14823
Inspection # 689303008**



Location Photo #5



Location Photo #6, Dripping fitting.

**Inspection Photo (s)
Specialty 43C
API # 05-045-14823
Inspection # 689303008**



Location Photo #7, Oil spot below fitting on 43C.

Location Photo #8

Inspection Photo (s)
Specialty 43C
API # 05-045-14823
Inspection # 689303008



Location Photo #9, leaking hammer union on separator 34C.