

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2019

Submitted Date:

01/17/2019

Document Number:

689302999**FIELD INSPECTION FORM**
 Loc ID 335119 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**24 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
Pesicka, Conor		conor.pesicka@state.co.us	
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277335	WELL	PR	11/24/2005	GW	045-10678	ANCHONDO 42B-20-692	PR
277336	WELL	PR	11/04/2005	GW	045-10679	ANCHONDO 42D-20-692	PR
277337	WELL	PR	12/29/2005	GW	045-10680	ANCHONDO 32D-20-692	PR
277338	WELL	PR	10/28/2005	GW	045-10681	ANCHONDO 32B-20-692	PR
290416	WELL	PR	05/03/2012	GW	045-14104	ANCHONDO 32A-20-692	PR
290417	WELL	PR	04/17/2012	GW	045-14103	ANCHONDO 32C-20-692	PR
290418	WELL	PR	10/09/2007	GW	045-14102	ANCHONDO 42A-20-692	PR
290419	WELL	PR	10/03/2007	GW	045-14101	ANCHONDO 42C-20-692	PR

General Comment:

Routine Field Inspection.

Location

Lease Road:			
Type	Access		
comment:	Snow packed.		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Umarked/ unused flow line riser, see photo.		
Corrective Action:	Comply with 603.f	Date:	02/17/2019
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel gates.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Water tansfer lines.		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	chemical unit at wellheads.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	HEATED STEEL AST		,
Comment:	4 tanks in a centralized battery. 2 tanks are non heated.				
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	YES	
Comment:	Bradenhead valves open to vent per sundry notice.	

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	277335	Type:	WELL	API Number:	045-10678	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	277336	Type:	WELL	API Number:	045-10679	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	277337	Type:	WELL	API Number:	045-10680	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	277338	Type:	WELL	API Number:	045-10681	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	290416	Type:	WELL	API Number:	045-14104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	290417	Type:	WELL	API Number:	045-14103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	290418	Type:	WELL	API Number:	045-14102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	290419	Type:	WELL	API Number:	045-14101	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303000	Inspection photo 689303000	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707336