

Inspection Photos
Location Name: AC 19-06
Location ID: 308934



Photo 1 SEP



Photo 2 stained soil around liquid ring compressor

Inspection Photos
Location Name: AC 19-06
Location ID: 308934



Photo 3 Stained soil around liquid ring compressor



**Photo 4 fluid leaking out of liquid ring skid via diaphr.
Stained soil under diaphr.**

Inspection Photos
Location Name: AC 19-06
Location ID: 308934



Photo 5 Stained soil around liquid ring compressor




Photo 6 stained soil around 30BBL H2O tank

Inspection Photos
Location Name: AC 19-06
Location ID: 308934



Photo 7 Unused equipment Methanol tank. Unused, unmarked and not LOTO riser.



Photo 8 Unused, unmarked and not LOTO risers

Inspection Photos
Location Name: AC 19-06
Location ID: 308934



Photo 9 stained soil in front of liquid ring compressor



Photo 10 soil sample taken in front of radiator of liquid ring compressor.