

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2019

Submitted Date:

01/17/2019

Document Number:

688401088

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
308063 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 12 Number of Comments  
5 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us	<a href="#">All Inspections</a>
Kosola, Jason		jason.kosola@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260689	WELL	PR	02/11/2003	GW	071-07468	APACHE CANYON 19-4VX	PR

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location sign		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil under 1" drain line for separator out of meter house.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	02/18/2019
Type	OTHER		
Comment:	Stained soil around liquid ring scrubber and around skid, motor skid and WH		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	01/21/2019
Type	TRASH		
Comment:	2x4s and Tpost next to separator laying on ground		
Corrective Action:	Comply with Rule 603.f .	Date:	01/31/2019
Type	OTHER		
Comment:	Self-inspection, maintenance and good house keeping procedures and schedules.		
Corrective Action:	Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs	Date:	01/21/2019
Type	OTHER		
Comment:	Materials handling and spill prevention procedures and practices.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B	Date:	01/21/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	liquid ring		
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	HYD motor skid		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	30BBL	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 260689 Type: WELL API Number: 071-07468 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Stained soil around liquid ring compressor appears to be from scrubber and around drain plug for skid.</a>	silverr	01/17/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401089	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707397</a>