

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2019

Submitted Date:

01/17/2019

Document Number:

688401090

FIELD INSPECTION FORM

Loc ID 308934 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	All Inspections
Ash, Margaret		margaret.ash@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285181	WELL	PR	02/25/2007	GW	071-08824	APACHE CANYON 19-6	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Location sign		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around liquid ring compressor , WH and 30BBL H2o tank		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A		Date: <u>01/21/2019</u>
Type	OTHER		
Comment:	Self-inspection, maintenance and good house keeping procedures and schedules.		
Corrective Action:	Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs		Date: <u>01/21/2019</u>
Type	OTHER		
Comment:	Materials handling and spill prevention procedures and practices.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B		Date: <u>01/21/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment Methanol tank		
Corrective Action:	Comply with Rule 603.f .		Date: <u>02/17/2019</u>
Type	OTHER		
Comment:	Unused, unmarked and not LOTO risers next to sep house and methanol tank		
Corrective Action:	Comply with COGCC rule 1103		Date: <u>02/17/2019</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		

Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Liquid ring. Well appears to be producing on a vacuum. No record of sundry recorded.		
Corrective Action:	Comply with COGCC rule 331.		Date: 02/18/2019
Type: Prime Mover	# 1		
Comment:	HYD motor skid		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	30BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment:	None			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	25BBL	

Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment: None				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 285181 Type: WELL API Number: 071-08824 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Stained soil in front of radiator appears to be dripping on ground via diaper. Took soil sample</u>	silverr	01/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401091	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707398
688401092	loc pic #2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707399