

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/11/2019

Submitted Date:

01/11/2019

Document Number:

679702547

**FIELD INSPECTION FORM**

Loc ID 315468 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone        | Email                           | Comment    |
|--------------------|--------------|---------------------------------|------------|
| Energy, Foundation |              | regulatory@foundationenergy.com | Regulatory |
| Waldron, Emily     |              | emily.waldron@state.co.us       |            |
| Kellerby, Shaun    | 970-712-1248 | shaun.kellerby@state.co.us      |            |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name             | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 230880      | WELL | PR     | 02/01/2017  | GW         | 103-08549 | TAIGA MTN FED 13-16-1-103 | PR          |

**General Comment:**

routine well inspection

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TANK LABELS/PLACARDS  |       |            |
| Comment:           | Sign or label not posted or information inaccurate on tanks or containers<br>Partially buried tank without label. |       |            |
| Corrective Action: | Install sign to comply with Rule 210.d.   | Date: | 03/15/2019 |
| Type               | WELLHEAD  |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | BATTERY   |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |

**Emergency Contact Number:**

Comment: 866-767-3600

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                              | #   |       | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Plunger Lift                | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Gas Meter Run               | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

**Tanks and Berms:**

| Contents       | # | Capacity | Type           | Tank ID | SE GPS                |
|----------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER | 1 | <50 BBLS | PBV FIBERGLASS |         | 39.966730,-108.968190 |
| Comment:       |   |          |                |         |                       |

|                    |       |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

**Paint**

|                  |          |  |  |
|------------------|----------|--|--|
| Condition        | Adequate |  |  |
| Other (Content)  |          |  |  |
| Other (Capacity) |          |  |  |
| Other (Type)     |          |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |  |       |
|--------------------|----|--|--|-------|
| Yes/No             | NO |  |  |       |
| Comment:           |    |  |  |       |
| Corrective Action: |    |  |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 230880 Type: WELL API Number: 103-08549 Status: PR Insp. Status: PR

**Producing Well**

Comment: [producing well on plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 | Compaction              |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401903048    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702264">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702264</a> |
| 679702548    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702251">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702251</a> |