

Inspection Photos
Location Name: GE 33-03
Location ID: 309417



Photo 1 SEP and liquid ring



Photo 2 WH

Inspection Photos
Location Name: GE 33-03
Location ID: 309417



Photo 3 Stained soil around liquid ring

Photo 4 stained soil and fluid dripping out of liquid ring skid

Inspection Photos
Location Name: GE 33-03
Location ID: 309417



Colorado Oil and Gas Conservation Commission
37.13422, -104.89425, 2240.0m
Jan 18, 2019 11:07:19

Photo 5 Stained soil around liquid ring and fluid dripping out of skid



Colorado Oil and Gas Conservation Commission
37.13424, -104.89429, 2247.0m
Jan 18, 2019 11:07:45

Photo 6 stained soil and fluid dripping out of liquid ring skid

Inspection Photos
Location Name: GE 33-03
Location ID: 309417



Colorado Oil and Gas Conservation Commission
37.13427, -104.89429, 2244.5m
Jan 18, 2019 11:08:09



Colorado Oil and Gas Conservation Commission
37.13424, -104.89438, 2249.1m
Jan 18, 2019 11:12:00

Photo 7 trash and debris inside liquid ring skid

Photo 8 soil sample taken where fluid is dripping out of skid

Inspection Photos
Location Name: GE 33-03
Location ID: 309417



Photo 9 electric fence around lined pit in disrepair

Photo 10 Unused, unmarked and not LOTO riser