

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/14/2019

Submitted Date:

01/14/2019

Document Number:

689302952

FIELD INSPECTION FORM

Loc ID 335321 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266772	WELL	PR	10/09/2003	GW	045-09181	ALP 25-9C (J25)	PR
266773	WELL	PR	10/09/2003	GW	045-09180	ALP 25-16 (J25)	PR
266774	WELL	PR	11/01/2012	GW	045-09179	ALP 25-8C (J25)	PR
266796	WELL	PR	10/12/2003	GW	045-09184	ALP 25-10 (J25)	PR
266797	WELL	PR	06/11/2004	GW	045-09183	ALP 25-9 (J25)	PR
281899	WELL	PR	05/27/2006	GW	045-11567	ALP 25-9D(J25NW)	PR
281901	WELL	PR	05/27/2006	GW	045-11568	ALP 25-8CI (J25NW)	PR

General Comment:

[Follow-up inspection from FIR DOC# 689302643 in response to FIRR DOC# 401883937 . Corrective actions have not been completed.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume			corrective date
Type: Plunger Lift	# 7				
Comment:					
Corrective Action:					Date:
Type: Vertical Heated Separator	# 7				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 3				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:	<input type="text" value="2 tanks in acentralized battery."/>				
Corrective Action:					Date:

Paint

Condition	<input type="text" value="Adequate"/>
Other (Content)	<input type="text" value="Methanol tank"/>
Other (Capacity)	<input type="text" value="1000 gallon"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	<input type="text" value="Hole in secndary liner near stair access, see photo."/>			
Corrective Action:	<input type="text" value="Repair or install berms or other secondary containment devices per Rule 906.d.(1)."/>			Date: <input type="text" value="01/14/2019"/>

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	500 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	266772	Type:	WELL	API Number:	045-09181	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	266773	Type:	WELL	API Number:	045-09180	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	266774	Type:	WELL	API Number:	045-09179	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	266796	Type:	WELL	API Number:	045-09184	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	266797	Type:	WELL	API Number:	045-09183	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	281899	Type:	WELL	API Number:	045-11567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	281901	Type:	WELL	API Number:	045-11568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401903355	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702740
689302953	Inspection photo 689302953	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4702731