

# Interim Reclamation and Stormwater Inspection

January 9, 2019

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 452874

Inspection Document #: 682404427

Weld County, CO

SWNW Section 26 T4N R63W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mustang /12-26 Pad  
Location ID: 452874



**Photo 1.** Photo taken from the entrance of the location, facing East. Photo illustrates Operator signs.



**Photo 2.** Photo taken from the southwest location, facing Southeast. Photo illustrates Russian thistle weed debris. More weed debris was observed along the southern and northern perimeter of the location.



Inspection Photos  
Location Name: Mustang /12-26 Pad  
Location ID: 452874



**Photo 3.** Photo taken from the eastern location, facing Northeast. Operator has performed interim reclamation activities with the evidence of drilling rows and straw crimped mulch. However, interim areas do not appear to be properly contoured to the surrounding landscape- see Photos 5 & 6.



**Photo 4.** Photo taken from the interim reclamation area. See comments under Photo 3.



Inspection Photos  
Location Name: Mustang /12-26 Pad  
Location ID: 452874



**Photo 5.** Photo taken from the southeastern interim area, facing South. Photo illustrates interim areas do not appear to be properly contoured to the surrounding landscape. Further review is required but Operator may need to perform additional contouring to comply with Rule 1003 standards.



Inspection Photos  
Location Name: Mustang /12-26 Pad  
Location ID: 452874



**Photo 6.** Photo taken from the southeastern perimeter of the location, facing North. See comments under Photo 5.

Inspection Photos  
Location Name: Mustang /12-26 Pad  
Location ID: 452874



**Photo 7.** Photo taken from the southeastern perimeter of the location, facing East. See comments under Photo 2.



**Photo 8.** Photo taken from the northern perimeter of the location, facing West. See comments under Photo 2.



Inspection Photos  
Location Name: Mustang /12-26 Pad  
Location ID: 452874



**Photo 9.** Photo taken from the northern location, facing West. Tackifier was observed on the cut slope but appears to be in need of maintenance. Also, remove any unused equipment from location.



**Photo 10.** Photo taken from the northwestern location, facing South. See comments under Photo 9.