

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2019

Submitted Date:

01/22/2019

Document Number:

689303018

**FIELD INSPECTION FORM**

Loc ID 335146 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259720	WELL	PR	04/04/2001	GW	045-07773	CLOUGH RWF 344-18	PR
265376	WELL	PR	04/28/2003	GW	045-09000	CLOUGH RWF 44-18	PR
273743	WELL	PR	04/24/2005	GW	045-10273	FEDERAL RWF 444-18	PR
273745	WELL	PR	04/20/2005	GW	045-10272	CLOUGH RWF 414-17	PR
286002	WELL	PR	08/02/2006	GW	045-12596	CLOUGH RWF 544-18	PR

**General Comment:**

This is a follow up inspection from Doc# 689302827. Required Corrective Action (s) items noted in previous inspections have been satisfied.  
Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	<u>259720</u>	Type:	<u>WELL</u>	API Number:	<u>045-07773</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>265376</u>	Type:	<u>WELL</u>	API Number:	<u>045-09000</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>273743</u>	Type:	<u>WELL</u>	API Number:	<u>045-10273</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>273745</u>	Type:	<u>WELL</u>	API Number:	<u>045-10272</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	
Facility ID:	<u>286002</u>	Type:	<u>WELL</u>	API Number:	<u>045-12596</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303019	Inspection photo 689303019	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710794">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710794</a>