

Inspection Photos

API: 05-009-06568

Operator: ENERGY ALLIANCE COMPANY

Inspection Date: 1/18/2019

Inspection Photos



Photo 1. Facing west at the location. Pipe risers have not been removed.

Inspection Photos



Photo 2. Pipe risers remain at the location.

Inspection Photos



Photo 3. Facing east at the location. At least 5 pipe risers remain.

Inspection Photos



Photo 4. GPS showing proximity to the location.