

Interim Reclamation and Stormwater Inspection

January 16, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 432988

Inspection Document #: 682404450

Weld County, CO

SWNW Section 5 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Union /11-5D
Location ID: 432988



Google Earth aerial imagery taken May 31, 2018. Imagery illustrates an area marked in red that does not appear to be needed for production operations. Also, there was stormwater erosion observed along the western and southwestern location discharging off location.

Inspection Photos
Location Name: Union /11-5D
Location ID: 432988



Photo 1. Photo taken from the southwestern well pad, facing West. Operator has failed to perform interim reclamation to reduce disturbance areas only needed for production operations. Also, there was stormwater erosion observed along the western and southwestern location discharging off location.

Inspection Photos
Location Name: Union /11-5D
Location ID: 432988



Photo 2. Photo taken from the southwestern well pad, facing South. Photo illustrates rill erosion discharging off location.

Inspection Photos
Location Name: Union /11-5D
Location ID: 432988



Photo 3. Photo taken from the southwestern well pad, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Union /11-5D
Location ID: 432988



Photo 4. Photo taken from the western well pad, facing West. See comments under Photo 2.