

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2019

Submitted Date:

01/22/2019

Document Number:

674301506

**FIELD INSPECTION FORM**

Loc ID 307190 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 52530  
Name of Operator: MAGPIE OPERATING, INC  
Address: 2707 SOUTH COUNTY RD 11  
City: LOVELAND State: CO Zip: 80537

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone        | Email                            | Comment |
|----------------|--------------|----------------------------------|---------|
| Pesicka, Conor |              | conor.pesicka@state.co.us        |         |
| Warner, Ryan   | 970-669-6308 | magpieoil@yahoo.com              |         |
| ,              |              | dnr_cogccengineering@state.co.us |         |
| Warner, Ross   |              | ross.magpieoil@gmail.com         |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 217108      | WELL | TA     | 10/01/2018  | OW         | 069-06295 | ANDERSON 2    | TA          |

**General Comment:**

[Form 42 #401898895](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |               |  |       |
|--------------------|---------------|--|-------|
|                    | Type WELLHEAD |  |       |
| Comment:           |               |  |       |
| Corrective Action: |               |  | Date: |

Emergency Contact Number:

|                    |  |  |             |
|--------------------|--|--|-------------|
| Comment:           |  |  |             |
| Corrective Action: |  |  | Date: _____ |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                |  |       |
|--------------------|----------------|--|-------|
|                    | Type PUMP JACK |  |       |
| Comment:           | Panel          |  |       |
| Corrective Action: |                |  | Date: |

**Equipment:**

|                          |                    |  |  |  | corrective date |
|--------------------------|--------------------|--|--|--|-----------------|
| Type: Pump Jack          | # 1                |  |  |  |                 |
| Comment:                 |                    |  |  |  |                 |
| Corrective Action:       |                    |  |  |  | Date:           |
| Type: Prime Mover        | # 1                |  |  |  |                 |
| Comment:                 | Natural gas engine |  |  |  |                 |
| Corrective Action:       |                    |  |  |  | Date:           |
| Type: Deadman # & Marked | # 4                |  |  |  |                 |
| Comment:                 |                    |  |  |  |                 |
| Corrective Action:       |                    |  |  |  | Date:           |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

Facility ID: 217108 Type: WELL API Number: 069-06295 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: MIT to maintain TA status. Perforations are 4601'-4839' KB, CIBP set @ 4560' KB. ICP @ 0 psig, Bradenhead @ 0 psig, MIRU hot oil truck, pressure csg to 450 psig and isolate wellbore from truck, 5 minute csg @ 440 psig, Bradenhead @ 0 psig, 10 minute csg @ 440 psig, Bradenhead @ 0 psig, 15 minute csg @ 440 psig, Bradenhead @ 0 psig, release pressure, RDMO truck, SIW.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 674301507    | Photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4712723">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4712723</a> |