

**Inspection Photo (s)**  
**Clough RWF 521-28**  
**API # 05-045-09921**  
**Inspection # 689303044**



**Location Photo #1**

