

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Adequate/Sign is fading but still can read		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type PUMP JACK		
Comment:	Angle Iron and Wire mesh		
Corrective Action:		Date:	

Equipment:

				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		
Type: Ancillary equipment	# 1			
Comment:	Small propane tank			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202208 Type: WELL API Number: 001-07613 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Appears to be shut-in

Corrective Action: Date:

BradenHead

Comment: Appears to be plumbed to surface

Corrective Action: Date:

COGCC Comments

Comment	User	Date
Routine Inspection	huckk	01/23/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400680	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713892