

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2019

Submitted Date:

01/24/2019

Document Number:

689303060**FIELD INSPECTION FORM**Loc ID 324144 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------------|---------|
| Coutts, Brandon | | bcoutts@mustangresourcesllc.com | |
| Lemon, Deb | | dlemon@mustangresourcesllc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 259159 | WELL | PR | 12/01/2016 | GW | 045-07696 | BURNS 9-35-6-94 W | PR |

General Comment:

Routine Field Inspection.

No facilities on location.

Location**Lease Road:**

| | | | |
|--------------------|---|-------|--|
| Type | Access | | |
| comment: | Access road in snow packed and not plowed open making access to location difficult. | | |
| Corrective ActionL | | Date: | |

Overall Good: ☐**Emergency Contact Number:**

| | | |
|--------------------|----------------|-------|
| Comment: | 1-888-291-8588 | |
| Corrective Action: | | Date: |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------------------|-------|--|
| Type | LOCATION | | |
| Comment: | 3 strand barbed wire. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------------|-----|-------|-----------------|
| Type: Deadman # & Marked | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | |
|-----------------------------|------------------------|------------------------------|---|
| Inspected Facilities | | | |
| Facility ID: <u>259159</u> | Type: <u>WELL</u> | API Number: <u>045-07696</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: | <u>Well producing.</u> | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Location is snow covered and not plowed open, making access to location difficult.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 689303061 | Inspection photo 689303061 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713908 |