



Inspection Photos
Operator Name: Bargath LLC
Facility ID: 460855



16" COPUC Gas Gathering Pipeline ruptured



Closer view of Pipeline ruptured area

Inspection Photos
Operator Name: Bargath LLC
Facility ID: 460855



16" COPUC Gas Gathering Pipeline ruptured