

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2019

Submitted Date:

01/24/2019

Document Number:

693200216**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Murray, Richard \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10128Name of Operator: BARGATH LLCAddress: 2717 COUNTY ROAD 215 SUITE 200City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Garrigues, Annette	970 285-5946	annette.garrigues@williams.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460855	SPILL OR RELEASE	AC	01/21/2019		-	16" Pipeline Release	AC

**General Comment:**

COGCC joint inspection with EPS S. Arauza and Western Integrity Inspector R. Murray.

Engineering Integrity Inspection performed on January 18, 2019. In response to initial form 19 spill report Doc #401910747

Flowline was shut in and secured at time of inspection

Ongoing clean up at time of inspection, Root cause to be determined

16" COPUC Gas Gathering Pipeline ruptured

**Inspected Facilities**Facility ID: 460855 Type: SPILL OR API Number: - Status: AC Insp. Status: AC**Flowline**

#1	Type:Non-Well Site	1 of Lines	
----	--------------------	------------	--

Flowline Description

Flowline Type: Non-Well Site Size: 16" Material: Carbon Steel  
 Variance: No Age: Contents: Natural Gas

Integrity Summary

Failures: Other Spills: Yes Repairs Made: No  
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: 16" COPUC Gas Gathering Pipeline ruptured, Root cause to be determined

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200217	Bargath	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714115">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714115</a>