

# Construction and Storm Water Inspection

January 2, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 456747

Inspection Document #: 674902397

Weld County, CO

SWNW Section 10 T1S R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S68W10

Location ID: 456747



**Photo 1.** Photo taken from the northwestern perimeter of the location, facing East. Photo illustrates a ditch and berm BMP that has been installed around the perimeter of the location.



**Photo 2.** Photo taken from the northwestern perimeter of the location, facing West. See comments from Photo 1.

## Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S68W10

Location ID: 456747



**Photo 3.** Photo taken from the northeastern perimeter of the location, facing East. See comments from Photo 1.



**Photo 4.** Photo taken from the northeastern perimeter of the location, facing West. See comments from Photo 1.



## Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S68W10

Location ID: 456747



**Photo 5.** Photo taken from the Eastern perimeter of the location, facing South. Operator has installed a sediment trap with a temporarily stabilized outlet. See comments from Photo 1.



**Photo 6.** Photo taken from the southern perimeter of the location, facing West. See comments from Photo 1.

## Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S68W10

Location ID: 456747



**Photo 7.** Photo taken from the southwestern perimeter of the location, facing West. The topsoil stockpile being stored along the eastern area has been temporarily stabilized with equipment tracking.



**Photo 8.** Photo taken from the western perimeter of the location, facing South. See comments under Photo 1.



## Inspection Photos

Location Name: EXTRACTION OIL & GAS INC – 10459/1S68W10

Location ID: 456747



**Photo 9.** Photo taken from the northern perimeter of the location, facing East. Operator has a street sweeper on site 24/7 during construction operations.



**Photo 10.** Photo taken from the access road, facing West. See comments from Photo 1.