

Inspection Photos
Location Name: RAZOR CLAM 23-27
Location ID: 308808



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: RAZOR CLAM 23-27
Location ID: 308808



PHOTO 3: STAINED SOIL UNDER DRAIN PLUG ON COMPRESSOR SKED.

PHOTO 4: STAINED SOIL NEAR WELLHEAD

Inspection Photos
Location Name: RAZOR CLAM 23-27
Location ID: 308808



PHOTO 3: STAINED SOIL AROUND WELLHEAD AND BETWEEN ENGINE SKID.