

Inspection Photos
Location Name: ERMELINDA 22-26
API #: 05-071-07006



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: ERMELINDA 22-26
API #: 05-071-07006



PHOTO 3: STAINED SOIL BETWEEN SOUND WALL AND WELLHEAD.



PHOTO 4: STAINED SOIL NEAR WELLHEAD.

Inspection Photos
Location Name: ERMELINDA 22-26
API #: 05-071-07006



**PHOTO 5: STAINED SOIL NEAR ENGINE SKID ON WEST SIDE
INSIDE SOUND WALL.**



**PHOTO 6: STAINED SOIL SPREADING UNDER SOUND WALL
ON WEST SIDE.**

Inspection Photos
Location Name: ERMELINDA 22-26
API #: 05-071-07006



Colorado Oil & Gas Conservation Commission
37.14539, -104.64376, 1967.0m, 70°
2019/01/24 12:15:47



Colorado Oil & Gas Conservation Commission
37.1453, -104.64364, 1969.0m, 111°
2019/01/24 12:17:23

PHOTO 7: DRAIN FROM SEPARATOR INSIDE METER HOUSE IS NO LONGER PLUMBED TO PRODUCED WATER TANK MAKING IT APPEAR THAT SEPARATOR IS BEEING DRAINED ON THE GROUND WHICH WOULD BE A COGCC RULE VIOLATION. CANNOT CONFIRM DUE TO SNOW COVERING GROUND IN THE VICINITY OF SEPARATOR DRAIN.

PHOTO 8: ANCHOR MARKER IS DOWN THIS IS A CORRECTIVE ACTION ON PREVIOUS INSPECTION DOC# 03636879