

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2019

Submitted Date:

01/24/2019

Document Number:

679702735**FIELD INSPECTION FORM**

Loc ID 316256 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 200502Name of Operator: 31 OPERATINGAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone        | Email                    | Comment |
|---------------|--------------|--------------------------|---------|
| Freeman, Kris | 254-727-0435 | kfreeman@31operating.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 259710      | WELL | PR     | 03/26/2001  | GW         | 103-10115 | WRD FEDERAL 21-33 | PR          |

**General Comment:**

routine well inspection

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 800-209-9762

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Deadman # & Marked  | # 3   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 1   |       |                 |
| Comment:                  | Container of methanol with secondary containment. |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Bird Protectors     | # 2   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Gas Meter Run       | # 1   |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Plunger Lift        | # 1   |       |                 |
| Comment:                  |   |       |                 |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 1 |       |  |
| Comment:                          |     |       |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |         |                       |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
| PRODUCED WATER     | 1 | 300 BBLS | STEEL AST |         | 40.125000,-108.167800 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |                       |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | 40.125000,-108.167800 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|          |  |
|----------|--|
| Type     |  |
| Comment: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

| Inspected Facilities |                                |       |      |             |           |         |    |               |    |
|----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 259710                         | Type: | WELL | API Number: | 103-10115 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                                |       |      |             |           |         |    |               |    |
| Comment:             | producing well on plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:   |                                |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 | Compaction              |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 679702736    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714328">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714328</a> |