

# Inspection Photos

1/18/2019

Operator: BAYHORSE PETROLEUM LLC - 10234

Location ID: 384908

Inspection Doc. Number: 682504424

Kiowa County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** 2017 Google Earth aerial image. Photo shows areas of the location (red polygon, ~4 acres) where vegetation has not achieved a uniform desirable perennial vegetative cover. Photo also shows access road. Access road remains predominantly bare and exposed soil.





**Photo 2:** Photo taken from the western end of the location, facing east. Photo shows large areas of the location that remains predominantly bare and exposed soil.



**Photo 3:** Photo taken from the western end of the location, facing southeast. See comments under photo 2.





**Photo 4:** Photo taken from the western end of the location, facing south. See comments under photo 2.



**Photo 5:** Photo taken from the western end of the location, facing east. See comments under photo 2.





**Photo 6:** Photo taken from the central areas of the location, facing south. Though there are patchy areas where vegetation establishment is occurring, location is largely bare and exposed soil.



**Photo 7:** Photo taken from the central areas of the location, facing south. See comments under photo 6.





**Photo 8:** Photo taken from the south-central area of the location, facing south. Photo shows large areas of the location that remains predominantly bare and exposed soil.



**Photo 9:** See comments under photo 8.





**Photo 10:** Photo taken from the southeastern end of the location, facing west. Photo shows areas where although there are patchy areas where vegetation establishment is occurring, vegetation establishment is not uniform throughout the location.





**Photo 11:** Photo taken from the southeastern end of the location, facing northwest.  
See comments under photo 12.





**Photo 12:** Photo taken from the southeastern end of the location, facing north. See comments under photo 12.



**Photo 13:** Photo taken from the northeastern end of the location, facing west. See comments under photo 12.





**Photo 14:** Photo taken from the north end of the location, facing north. Photo shows access road. Though there are areas of the access road where vegetation establishment is occurring, vegetation establishment is not uniform; access road remains predominantly bare and exposed soil.





**Photo 15:** Photo taken from the north end of the access road, facing south. See comments under photo 16.