

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2019

Submitted Date:

01/25/2019

Document Number:

689303064**FIELD INSPECTION FORM**

Loc ID 334892	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 10 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262862	WELL	PR	10/03/2002	GW	045-08060	SHIDELER 32-11A2 (G32NEB)	PR
262863	WELL	PR	02/01/2008	GW	045-08061	SHIDELER 32-6A2 (G32NEB)	PR
262864	WELL	PR	02/24/2003	GW	045-08062	SHIDELER 32-3D2 (G32NED)	PR
262865	WELL	PR	10/01/2018	GW	045-08063	SHIDELER 32-1C3 (G32NED)	PR
262893	WELL	PR	10/03/2002	GW	045-08070	SHIDELER 32-10A2 (G32NEB)	PR
262894	WELL	PR	02/22/2003	GW	045-08071	SHIDELER 32-1B2 (G32NED)	PR
262895	WELL	PR	09/30/2002	GW	045-08072	SHIDELER 32-9B2 (G32NEB)	PR

**General Comment:**

This is a follow up inspection from Doc# 689302691. Required Corrective Action (s) items noted in previous inspections have been satisfied.  
Equipment inventory has not changed on location.

Inspected Facilities						
Facility ID:	262862	Type:	WELL	API Number: 045-08060	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Well Producing on plunger lift.					
Corrective Action:						Date:
Facility ID:	262863	Type:	WELL	API Number: 045-08061	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Well Producing on plunger lift.					
Corrective Action:						Date:
Facility ID:	262864	Type:	WELL	API Number: 045-08062	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Well Producing on plunger lift.					
Corrective Action:						Date:
Facility ID:	262865	Type:	WELL	API Number: 045-08063	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Well Producing on plunger lift.					
Corrective Action:						Date:
Facility ID:	262893	Type:	WELL	API Number: 045-08070	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Well Producing on plunger lift.					
Corrective Action:						Date:
Facility ID:	262894	Type:	WELL	API Number: 045-08071	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Well Producing on plunger lift.					
Corrective Action:						Date:
Facility ID:	262895	Type:	WELL	API Number: 045-08072	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Well Producing on plunger lift.					
Corrective Action:						Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303065	Inspection photo 689303065	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715518">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715518</a>