

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2019

Submitted Date:

01/25/2019

Document Number:

689303072**FIELD INSPECTION FORM**Loc ID 334560 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199992	WELL	PR	03/23/2004	GW	045-07409	KRK 7-6 (C7)	PR
199994	WELL	PR	01/20/2005	GW	045-07407	KRK 6-14(C7)	PR
199995	WELL	PR	03/24/2004	GW	045-07406	SHAEFFER 12-1 (C7)	PR
211240	WELL	PR	09/20/1995	GW	045-06999	KRK LTD 7-3	PR
277268	WELL	PR	03/06/2006	GW	045-10649	KRK 6-14C (C7E)	PR
277270	WELL	PR	06/06/2006	GW	045-10647	KRK 7-3A (C7E)	PR
277272	WELL	PR	03/04/2006	GW	045-10646	KRK 12-8A (C7E)	PR

General Comment:

This is a follow up inspection from [Doc# 689302772](#). Required Corrective Action (s) items noted in previous inspections have been satisfied.

Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	199992	Type:	WELL	API Number:	045-07409	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	199994	Type:	WELL	API Number:	045-07407	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	199995	Type:	WELL	API Number:	045-07406	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	211240	Type:	WELL	API Number:	045-06999	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing.								
Corrective Action:						Date:			
Facility ID:	277268	Type:	WELL	API Number:	045-10649	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	277270	Type:	WELL	API Number:	045-10647	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	277272	Type:	WELL	API Number:	045-10646	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303073	Inspection photo 689303073	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715522