

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/25/2019

Submitted Date:

01/25/2019

Document Number:

689303074

**FIELD INSPECTION FORM**

Loc ID 334801 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199993	WELL	PR	05/08/2000	GW	045-07408	BENZEL 1-9	PR
256350	WELL	PR	11/10/1999	GW	045-07445	BJM 6-11 (I 1)	PR
256351	WELL	PR	09/14/2000	GW	045-07446	BENZEL 1-16(I1)	PR

**General Comment:**

This is a follow up inspection from Doc# 68902862. Required Corrective Action (s) items noted in previous inspections have been satisfied. Equipment inventory has not changed on location.

**Inspected Facilities**

Facility ID: 199993 Type: WELL API Number: 045-07408 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 256350 Type: WELL API Number: 045-07445 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

Facility ID: 256351 Type: WELL API Number: 045-07446 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303078	Inspection photo 689303078	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715523">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715523</a>