

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2019

Submitted Date:

01/25/2019

Document Number:

689303076**FIELD INSPECTION FORM**Loc ID 334966 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275233	WELL	PR	07/01/2018	GW	045-13489	BJM 31-6C(H36NW)	PR
275234	WELL	PR	03/09/2007	GW	045-13490	BENZEL 36-9A(H36NW)	PR
284532	WELL	PR	03/16/2007	GW	045-12197	BENZEL 36-1A (H36NW)	PR

**General Comment:**

This is a follow up inspection from Doc# 689302852. Required Corrective Action (s) items noted in previous inspections have been satisfied.

Equipment inventory has not changed on location.

Inspected Facilities				
Facility ID: 275233	Type: WELL	API Number: 045-13489	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Well Producing on plunger lift.			
Corrective Action:				Date:
Facility ID: 275234	Type: WELL	API Number: 045-13490	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Well Producing on plunger lift.			
Corrective Action:				Date:
Facility ID: 284532	Type: WELL	API Number: 045-12197	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Well Producing on plunger lift.			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303077	Inspection photo 689303077	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715524</a>