

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2019

Submitted Date:

01/28/2019

Document Number:

689303096

**FIELD INSPECTION FORM**

Loc ID 335155 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287320	WELL	PR	07/16/2008	GW	045-12971	BROCK 19-06D	PR
287324	WELL	PR	10/10/2007	GW	045-12967	BROCK 19-05B	PR
287325	WELL	PR	06/11/2009	GW	045-12966	BROCK 19-03D	PR
287326	WELL	PR	10/10/2007	GW	045-12965	BROCK 19-04B	PR

**General Comment:**

[Routine Field Inspection.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Snow packed.		
Corrective Action:			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-891-6191		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panel fence.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellheads.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	STEEL AST		,
Comment:	250 BBL tanks				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 287320 Type: WELL API Number: 045-12971 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 287324 Type: WELL API Number: 045-12967 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 287325 Type: WELL API Number: 045-12966 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

Facility ID: 287326 Type: WELL API Number: 045-12965 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303097	Inspection photo 689303097	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4717090">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4717090</a>