

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2019

Submitted Date:

01/28/2019

Document Number:

696100011**FIELD INSPECTION FORM**Loc ID 414899 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414914	WELL	SI	04/01/2017	OW	123-30887	IGO FARMS J 28-19D	PR
414917	WELL	PR	08/01/2018	GW	123-30889	IGO FARMS J 28-20D	SI
414919	WELL	PR	08/01/2018	OW	123-30891	IGO FARMS J 28-32D	PR
414925	WELL	PR	08/01/2018	OW	123-30895	IGO FARMS J 28-31D	SI

**General Comment:**

This is a WELL inspection. (4 - wells).  
 Centralized Battery serves 3 location IDs (326999, 327000, 414899).  
 Refer to FIR #696100007 and/or Location ID #326999 for Battery / Facility, Equipment info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	OTHER		

Comment:	Refer to FIR #696100007 and/or Location ID #326999 for additional Fencing info.			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Iron panel			
Corrective Action:			Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	Refer to FIR #696100007 and/or Location ID #326999 for additional Equipment info.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.375677,-104.791886	
Comment:	Centralized Battery serves 3 location IDs (326999, 327000, 414899). Refer to FIR #696100007 and/or Location ID #326999 for Tanks & Berms info.					
Corrective Action:						Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 414914 Type: WELL API Number: 123-30887 Status: SI Insp. Status: PR

**Producing Well**Comment: PR.

Corrective Action:

Date:

**BradenHead**Comment: Bradenhead appears plumbed to surface.

Corrective Action:

Date:

Facility ID: 414917 Type: WELL API Number: 123-30889 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: SI at separator.

Corrective Action:

Date:

**BradenHead**Comment: Bradenhead appears plumbed to surface.

Corrective Action:

Date:

Facility ID: 414919 Type: WELL API Number: 123-30891 Status: PR Insp. Status: PR

**Producing Well**Comment: PR.

Corrective Action:

Date:

**BradenHead**Comment: Bradenhead appears plumbed to surface.

Corrective Action:

Date:

Facility ID: 414925 Type: WELL API Number: 123-30895 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment: SI at separator.

Corrective Action:

Date:

**BradenHead**Comment: Bradenhead appears plumbed to surface.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100012	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4717273">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4717273</a>