



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Prime Mover	# 1				
Comment:	gas powered motor				
Corrective Action:			Date:		
Type: Pump Jack	# 1				
Comment:					
Corrective Action:			Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203533 Type: WELL API Number: 001-09093 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
This is a follow up inspection per Doc#688302468. All corrective actions have been addressed at time of inspection.	silverr	01/29/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688401145	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720201">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720201</a>