

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2019

Submitted Date:

01/24/2019

Document Number:

689303056**FIELD INSPECTION FORM**

Loc ID 323894	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> 11 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211113	WELL	PR	03/29/2010	GW	045-06872	BARRETT RMV 20-35	PR
439666	WELL	XX	10/17/2016	LO	045-22552	Huggard RWF 34-35	ND
439667	WELL	XX	10/17/2016	LO	045-22553	Huggard RWF 334-35	ND
439668	WELL	XX	10/17/2016	LO	045-22554	Huggard RWF 443-35	ND
439669	WELL	XX	10/17/2016	LO	045-22555	Huggard RWF 43-35	ND
439670	WELL	XX	10/17/2016	LO	045-22556	Huggard RWF 44-35	ND
439671	WELL	XX	10/17/2016	LO	045-22557	Huggard RWF 343-35	ND
439672	WELL	XX	10/17/2016	LO	045-22558	Huggard RWF 33-35	ND
439673	WELL	XX	10/17/2016	LO	045-22559	Huggard RMV 70-35	ND
439674	WELL	XX	10/17/2016	LO	045-22560	Huggard RWF 333-35	ND
439675	WELL	XX	10/17/2016	LO	045-22561	Huggard RWF 433-35	ND
439676	WELL	XX	10/17/2016	LO	045-22562	Huggard RWF 344-35	ND
439677	WELL	XX	10/17/2016	LO	045-22563	Huggard RMV 117-35	ND

<b>General Comment:</b> <u>Routine Field Inspection.</u>
---

**Location****Lease Road:**

Type	Access		
comment:	Snow packed and not plowed open. Hard to access location.		
Corrective Action:		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:	1-970-285-9377		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	2" grey Balon Ball valve has a small leak, see photo.		

Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	02/24/2019
Type: Ancillary equipment	# 1			
Comment:	Chemical unit at separator.			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID:	211113	Type:	WELL	API Number: 045-06872 Status: PR Insp. Status: PR
Producing Well				
Comment:	Well Producing on plunger lift.			
Corrective Action:				Date:
Facility ID:	439666	Type:	WELL	API Number: 045-22552 Status: XX Insp. Status: ND
Facility ID:	439667	Type:	WELL	API Number: 045-22553 Status: XX Insp. Status: ND
Facility ID:	439668	Type:	WELL	API Number: 045-22554 Status: XX Insp. Status: ND
Facility ID:	439669	Type:	WELL	API Number: 045-22555 Status: XX Insp. Status: ND
Facility ID:	439670	Type:	WELL	API Number: 045-22556 Status: XX Insp. Status: ND
Facility ID:	439671	Type:	WELL	API Number: 045-22557 Status: XX Insp. Status: ND
Facility ID:	439672	Type:	WELL	API Number: 045-22558 Status: XX Insp. Status: ND
Facility ID:	439673	Type:	WELL	API Number: 045-22559 Status: XX Insp. Status: ND
Facility ID:	439674	Type:	WELL	API Number: 045-22560 Status: XX Insp. Status: ND
Facility ID:	439675	Type:	WELL	API Number: 045-22561 Status: XX Insp. Status: ND
Facility ID:	439676	Type:	WELL	API Number: 045-22562 Status: XX Insp. Status: ND
Facility ID:	439677	Type:	WELL	API Number: 045-22563 Status: XX Insp. Status: ND

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401917122	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713917</a>
689303057	Inspection photo 689303057	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713904">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713904</a>