

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2019

Submitted Date:

01/24/2019

Document Number:

695100078**FIELD INSPECTION FORM**Loc ID 307822 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Natural, Pioneer		COGCC.Inspections@pxd.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257179	WELL	PR	06/19/2003	GW	071-07006	ERMELINDA 22-26	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PRODUCED WATER TANK LABEL		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	STAINED SOIL BETWEEN SOUND WALL AND WELLHEAD. STAINED SOIL NEAR WELLHEAD. STAINED SOIL NEAR ENGINE SKID ON WEST SIDE INSIDE SOUND WALL. STAINED SOIL SPREADING UNDER SOUND WALL ON WEST SIDE.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.	Date:	02/25/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	ANCHOR MARKER IS DOWN THIS IS A CORRECTIVE ACTION ON PREVIOUS INSPECTION DOC# 03636879		
Corrective Action:	Mark guy line anchors per Rule 1003. a.	Date:	01/31/2019
Type: Compressor	# 0		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PLASTIC AST		37.145220,-104.643750	

Comment: DRAIN FROM SEPARATOR INSIDE METER HOUSE IS NO LONGER PLUMBED TO PRODUCED WATER TANK MAKING IT APPEAR THAT SEPARATOR IS BEEING DRAINED ON THE GROUND WHICH WOULD BE A COGCC RULE VIOLATION. CANNOT CONFIRM DUE TO SNOW COVERING GROUND IN THE VICINITY OF SEPARATOR DRAIN.

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	30 GAL.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 257179 Type: WELL API Number: 071-07006 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Comment: PLUMBED TO SURFACECorrective Action: Date: **COGCC Comments**

Comment	User	Date
<u>THIS IS A FALLOW UP INSPECTION TO INSP. DOC# 68790363. CORRECTIVE ACTION HAS NOT BEEN COMPLETED.</u>	beardslt	01/24/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401917640	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714346
695100079	LOC PICS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4714336