

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/30/2019

Submitted Date:

01/30/2019

Document Number:

689303120**FIELD INSPECTION FORM**
 Loc ID 324196 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	Pipeline group
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264267	WELL	PR	12/16/2002	GW	045-08195	GMR 21-10B(21)	PR

General Comment:[Routine Field Inspection.](#)

Location				
Lease Road:				
Type	Access			
comment:	Snow packed.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	1-800-791-7691			
Corrective Action:				Date:
Good Housekeeping:				
Type	DEBRIS			
Comment:				
Corrective Action:				Date:
Type	UNUSED EQUIPMENT			
Comment:	1) unused pipe next to separator, see photo. 2) Unmarked, unused flowline riser, see photo.			
Corrective Action:	1) Comply with 603.f. 2) Comply with 603.f., For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser			Date: 03/04/2019
Type	TRASH			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Concrete barriers.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	264267	Type:	WELL	API Number:	045-08195	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:				Date:					

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303121	Inspection photo 689303121	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720307