

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2019

Submitted Date:

01/30/2019

Document Number:

689303128

**FIELD INSPECTION FORM**

Loc ID 335399 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299111	WELL	PR	09/30/2009	GW	045-17563	GMR 33-2D1(G33NW)	PR
299149	WELL	PR	09/30/2009	GW	045-17575	GMR 34-12B(G33NW)	PR
299150	WELL	PR	01/19/2010	GW	045-17576	GMR 33-2D(G33NW)	PR
299151	WELL	PR	09/30/2009	GW	045-17577	GMR 33-8(G33NW)	PR
299158	WELL	PR	09/30/2009	GW	045-17578	GMR 33-10A(G33NW)	PR
299159	WELL	PR	09/26/2009	GW	045-17579	GMU 33-3D1(G33NW)	PR

**General Comment:**

[Routine Field Inspection.](#)  
[Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Snow packed.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:		Date:	_____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Unmarked flow line riser behind separators.		
Corrective Action:	Comply with 603.f. For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser	Date:	03/04/2019
Type	OTHER		
Comment:	Stained ground in battery containment and next to the North side of the verticle separators, see photos.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e..	Date:	03/04/2019
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	sheep fence.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		
Comment:	Mechanical condition of tank valves, see photo.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 03/04/2019

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	299111	Type:	WELL	API Number:	045-17563	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299149	Type:	WELL	API Number:	045-17575	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299150	Type:	WELL	API Number:	045-17576	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299151	Type:	WELL	API Number:	045-17577	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299158	Type:	WELL	API Number:	045-17578	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	299159	Type:	WELL	API Number:	045-17579	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303129	Inspection photo 689303129	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720311">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720311</a>