

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2019

Submitted Date:

01/31/2019

Document Number:

687903701**FIELD INSPECTION FORM**Loc ID 306890 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre		sabre.beebe@bp.com	All Inspections
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274089	WELL	PR	08/01/2018	GW	067-08982	DWIGHT SOSSAMAN A 2	PR

General Comment:[Downloadable photos in the end of this report.](#)

Location**Lease Road:**

Type	Access		
comment:	Gravel road.		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Framed metal sign at entry into location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	emergency contact information up to date. (970) 247-6919/911	
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Cattle panel.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	post and barb wire.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	wellhead.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,

Comment:	Tank capacity, contents and NFPA placard on tank and framed metal sign.		
Corrective Action:		Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 274089 Type: WELL API Number: 067-08982 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: COGIS database information shows well is producing as of 8-1-2018. Upon inspection, wellhead and meter run are shut-in and LOTO.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903702	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720430
687903703	Equipment on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720431
687903705	Equipment on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720432
687903706	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720433