

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2019

Submitted Date:

01/31/2019

Document Number:

690101025

**FIELD INSPECTION FORM**Loc ID 319865 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extractionog.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Ford, Blake		bford@extractionog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201650	WELL	SI	04/01/2015	OW	001-07053	AYLOR 2	EG

**General Comment:**

COGCC Engineering Integrity Inspection; Well has been plugged and abandoned (Aylor 2). Details of observation made during this field inspection are outlined in the flowline section of report. Photos uploaded.

**Inspected Facilities**

Facility ID: 201650 Type: WELL API Number: 001-07053 Status: SI Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: The entire off location/ wellhead flowline (approximately 1800' in length/ 2" orange poly) has been excavated and removed. The Aylor 2 dump flowlines and process pipe have been removed. No inactive flowline risers are present. COGCC form 44 notice of flowlines abandoned (removed) doc #401923009 was received on 1/30/19. Excavation and remediation activities adjacent to the (PA) wellhead are ongoing.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
COGCC Form 19 spill report Doc #401914968 was received on 01/23/2019 and states the following: While conducting remediation work, potential surface staining was discovered. The entire site is being decommissioned and will be reclaimed. More details will follow in an Form 19 supplemental submittal pending further investigation.	maclarej	01/31/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101028	Signage at tank battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4721651">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4721651</a>
690101029	Excavation and remediation work (near PA wellhead)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4721652">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4721652</a>
690101030	Trash bin containing orange poly flowline (removed)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4721653">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4721653</a>