

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2019

Submitted Date:

01/17/2019

Document Number:

688401090**FIELD INSPECTION FORM**

Loc ID 308934 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285181	WELL	PR	02/25/2007	GW	071-08824	APACHE CANYON 19-6	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Location sign		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Materials handling and spill prevention procedures and practices.		
Corrective Action:	Comply with COGCC rule 1002 F (2) B	Date:	01/21/2019
Type	OTHER		
Comment:	Self-inspection, maintenance and good house keeping procedures and schedules.		
Corrective Action:	Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs	Date:	01/21/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment Methanol tank		
Corrective Action:	Comply with Rule 603.f .	Date:	02/17/2019
Type	OTHER		
Comment:	Unused, unmarked and not LOTO risers next to sep house and methanol tank		
Corrective Action:	Comply with COGCC rule 1103	Date:	02/17/2019
Type	OTHER		
Comment:	Stained soil around liquid ring compressor , WH and 30BBL H2o tank		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A	Date:	01/21/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Progressive Cavity	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:		Date:	
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Liquid ring. Well appears to be producing on a vacuum. No record of sundry recorded.	Date:	02/18/2019
Corrective Action:	Comply with COGCC rule 331.	Date:	02/18/2019
Type: Prime Mover	# 1		
Comment:	HYD motor skid	Date:	
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	25BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment:	None			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	30BBL

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other					
Comment: None					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected FacilitiesFacility ID: 285181 Type: WELL API Number: 071-08824 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Stained soil in front of radiator appears to be dripping on ground via diaper. Took soil sample</u>	silverr	01/17/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401909868	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707411
688401091	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707398
688401092	loc pic #2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707399