

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/01/2019

Submitted Date:

02/01/2019

Document Number:

689303134

FIELD INSPECTION FORM

Loc ID 335185 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210958	WELL	PR	08/18/1995	GW	045-06716	JOLLEY 20-6 1	PR
289479	WELL	PR	08/04/2009	GW	045-13772	GGU JOLLEY 44C-20-691	PR
289480	WELL	PR	06/29/2007	GW	045-13771	GGU JOLLEY 44A-20-691	PR
289777	WELL	PR	07/16/2009	GW	045-13881	GGU JOLLEY 43B-20-691	PR
289778	WELL	PR	07/07/2007	GW	045-13880	GGU JOLLEY 43D-20-691	PR

General Comment:

This is a follow up inspection from Doc# 689302655. Required Corrective Action (s) items noted in previous inspections have been satisfied.
Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	<u>210958</u>	Type:	<u>WELL</u>	API Number:	<u>045-06716</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>289479</u>	Type:	<u>WELL</u>	API Number:	<u>045-13772</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>289480</u>	Type:	<u>WELL</u>	API Number:	<u>045-13771</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>289777</u>	Type:	<u>WELL</u>	API Number:	<u>045-13881</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				
Facility ID:	<u>289778</u>	Type:	<u>WELL</u>	API Number:	<u>045-13880</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>Well Producing on plunger lift.</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303135	Inspection photo 689303135	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4723372