

**Inspection Photo (s)**  
**Clough 134**  
**API # 05-045-06270**  
**Inspection # 689303160**



**Location Photo #1**



**Location Photo #2, non legible sign on meter run.**