

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2019

Submitted Date:

02/06/2019

Document Number:

696100072

FIELD INSPECTION FORM

Loc ID 306743 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Barbula, Don		dbarbula@bayswater.us	all inspections
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290643	WELL	SI	10/01/2018	OW	123-25183	HESTER 31-23	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** Inspection.
 Centralized Battery presently exists & serves 4 Location IDs (306151, 305997, 309702, 310194).
 Centralized Battery formerly served this P&A well Location ID (306743).
 Refer to FIR #696100064 and/or Location ID #306151 for Battery / Facility, Equipment info.
 Well is PA.
 Battery & ALL equipment is Shut-down.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 290643 Type: WELL API Number: 123-25183 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Plugged & Abandoned.
 Form 42 #401871102 indicates plugging operations were planned to commence on 12/13/2018.
 Casing has NOT been cutoff & capped. No temporary safety casing cap is installed.
 Casing remains exposed approximately 18" above ground surface.
 Cement does NOT appear inside of open casing.
 Refer to Rule 605.c for guidance regarding special equipment requirements for public safety.

Corrective Action: Cutoff & permanently cap casing and/or install a temporary casing safety cap.
 Comply with Rule 605.c.

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100073	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726715