

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2019

Submitted Date:

02/07/2019

Document Number:

687903753**FIELD INSPECTION FORM**Loc ID 325517 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214931	WELL	PR	12/01/2010	GW	067-06536	DAVIS 01-28 1	PR

General Comment:[Downloadable photos at the end of this inspection report.](#) [Location covered in snow during time of inspection.](#)

Location**Lease Road:**

Type	Access		
comment:	Gravel road.		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Metal framed sign at entrance to location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Contact information is correct. (970) 247-6916/911	Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels around well head.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Wellhead has small leak on main flange. Contacted BP's 24 HR number and reported leak.		
Corrective Action:	Please comply with Rule 605.d		Date: 02/08/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 214931 Type: WELL API Number: 067-06536 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903754	Wellhead leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728159
687903755	Equipment photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728160
687903756	Wellhead leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728161
687903757	Location sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728162