

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2019

Submitted Date:

02/07/2019

Document Number:

687903742**FIELD INSPECTION FORM**

Loc ID 333767 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273108	WELL	PR	12/07/2004	GW	067-08958	MCCAW 34-15 2	PR
296171	WELL	PR	05/27/2008	GW	067-09563	MCCAW 34-15 4	PR

General Comment:

[Downloadable pictures at end of inspection report.](#) Location covered in snow during time of inspection.

Location				
Lease Road:				
	Type	Access		
	comment:	Gravel access road.		
	Corrective Action:			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
	Type	WELLHEAD		
	Comment:	Metal framed sign at entry to location.		
	Corrective Action:			Date:
Emergency Contact Number:				
	Comment:	Emergency contact number up to date. (970) 247-6916/911		
	Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type	WELLHEAD		
	Comment:	Cattle panel around wellhead and pump jack.		
	Corrective Action:			Date:
	Type	SEPARATOR		
	Comment:	Cattle panel around seperator, pit and meter house.		
	Corrective Action:			Date:
Equipment:				
				corrective date
Type:	Horizontal Heated Separator	# 1		
	Comment:			
	Corrective Action:			Date:
Type:	Pump Jack	# 1		
	Comment:			
	Corrective Action:			Date:
Type:	Gas Meter Run	# 2		
	Comment:			
	Corrective Action:			Date:
Type:	Bird Protectors	# 2		
	Comment:			
	Corrective Action:			Date:

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Wellhead		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	PBV STEEL		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected FacilitiesFacility ID: 273108 Type: WELL API Number: 067-08958 Status: PR Insp. Status: PRFacility ID: 296171 Type: WELL API Number: 067-09563 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903743	Location entrance	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728154
687903744	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728155