

Inspection Photo (s)
Miller 43B
API # 05-045-17933
Inspection # 689303186



Location Photo #1



Location Photo #2

Inspection Photo (s)
Miller 43B
API # 05-045-17933
Inspection # 689303186



Location Photo #3



Location Photo #4, Dripping master valve.

Inspection Photo (s)
Miller 43B
API # 05-045-17933
Inspection # 689303186



Location Photo #5, stained ground below master valve.



Location Photo #6, Leaking packing on master valve.

Inspection Photo (s)
Miller 43B
API # 05-045-17933
Inspection # 689303186



Location Photo #7, Mechanical condition of master valve.