

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2019

Submitted Date:

02/07/2019

Document Number:

689303184**FIELD INSPECTION FORM**Loc ID: 423439 Inspector Name: Holtz, Darin On-Site Inspection: ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**22 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412841	WELL	PR	07/21/2011	GW	045-18667	MILLER 33D-6-791	PR
412843	WELL	PR	07/21/2011	GW	045-18666	MILLER 33C-6-791	PR
412844	WELL	PR	06/06/2011	GW	045-18665	MILLER 33B-6-791	PR
412845	WELL	PR	06/06/2011	GW	045-18664	MILLER 33A-6-791	PR
412846	WELL	PR	07/21/2011	GW	045-18663	MILLER FEDERAL 23D-6-791	PR
412847	WELL	PR	06/06/2011	GW	045-18662	MILLER FEDERAL 23C-6-791	PR
412848	WELL	PR	06/06/2011	GW	045-18661	MILLER FEDERAL 23B-6-791	PR
412849	WELL	PR	07/20/2011	GW	045-18660	MILLER FEDERAL 24D-31-691	PR
412850	WELL	PR	07/20/2011	GW	045-18659	MILLER FEDERAL 24C-31-691	PR
412853	WELL	PR	07/21/2011	GW	045-18657	MILLER FEDERAL 24A-31-691	PR
412910	WELL	PR	07/21/2011	GW	045-18658	MILLER FEDERAL 24B 31-691	PR

**General Comment:**Routine Field Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Snow packed, plowed open.		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-921-8252

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 6		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical units at wellheads.		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	YES		
Comment:	Bradenhead valves open top vent per sundry notice.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	412841	Type:	WELL	API Number:	045-18667	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	412843	Type:	WELL	API Number:	045-18666	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	412844	Type:	WELL	API Number:	045-18665	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	412845	Type:	WELL	API Number:	045-18664	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	412846	Type:	WELL	API Number:	045-18663	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	412847	Type:	WELL	API Number:	045-18662	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	412848	Type:	WELL	API Number:	045-18661	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	412849	Type:	WELL	API Number:	045-18660	Status:	PR	Insp. Status:	PR

<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID: 412850    Type: WELL    API Number: 045-18659    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID: 412853    Type: WELL    API Number: 045-18657    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID: 412910    Type: WELL    API Number: 045-18658    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303185	Inspection photo 689303185	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728315">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728315</a>