

# *Inspection Photos*

*Loc#335879*

*Operator: Ursa*

*Inspection Number: 692400636*

*Inspection Date: 1/31/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Southwest.

January 31, 2019



Photo#2:  
Overview of Cuttings area to Northeast.



Photo#3:

Line indicates where BMP perimeter control is needed on West side, along fill slope of cuttings area.

January 31, 2019



Photo#4:

Tracking pad not installed on Cuttings area entry road.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Loc#335879





Photo#5:  
Vegetation establishment on slopes is largely unsuccessful.

January 31, 2019



Photo#6:  
Vegetation establishment on slopes is largely unsuccessful. Insert of netting Debris



Photo#7:

Pit area has infestation of Russian Thistle. Insert is of Thistle that has become Debris.

January 31, 2019



Photo#8:

Pit area has infestation of Russian Thistle. Arrow indicates unstable area of Cut Slope.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Loc#335879