

Inspection Photos
Location Name: TADPOLE 21-12
API #: 05-071-06671
Insp. Doc. # 695100147



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: TADPOLE 21-12
API #: 05-071-06671
Insp. Doc. # 695100147



PHOTO 3: STAINED SOIL NEAR PRIME MOVER ON PUMP JACK SKID.



PHOTO 4: STAINED SOIL NEAR PUMP JACK GEAR BOX

Inspection Photos
Location Name: TADPOLE 21-12
API #: 05-071-06671
Insp. Doc. # 695100147

Calibration Report

Report Date: 10/19/18 1:03 PM Collection Time: 10/19/18 1:00 PM

Well ID: 106106671 System: Contact # 719-846-7898
Location: TADPOLE 21-12 Field: Raton Basin
State: Colorado
Producer: Evergreen Natural Resources
Purchaser: Colorado Interstate Gas

Current Plate Size: 0.5 Tap Type: Flange Specific Gravity: 0.569
Pipe Size: 2.067 SP Tap Location: Down Stream
Atmos. Pressure: 11.41 Temperature Bias: 1.8
Pressure Base: 14.73 Temperature Base: 60

Plate Inspected? ☒ Yes ☐ No Dirty ☒ Yes ☐ No Nicked? ☒ Yes ☐ No
Edges Sharp? ☒ Yes ☐ No Plate Mic'd ☒ Yes ☐ No Warped? ☒ Yes ☐ No
Seal Ring Damaged? ☒ Yes ☐ No Pitted ☒ Yes ☐ No Bevel Downstream ☒ Yes ☐ No

Master Tube Inspection
Tube Inspected? ☒ Yes ☐ No Air-bled? ☒ Yes ☐ No
Dirty? ☒ Yes ☐ No
Pitted? ☒ Yes ☐ No

Static Pressure

FOUND	LEFT	FOUND	LEFT	FOUND	LEFT
0.00	24.97	0.00	24.97	0.00	24.97
25.00	49.94	25.00	49.94	25.00	49.94
50.00	74.91	50.00	74.91	50.00	74.91
75.00	99.88	75.00	99.88	75.00	99.88
100.00	124.85	100.00	124.85	100.00	124.85

Colorado Oil & Gas Conservation Commission
37.10382, -104.73419, 2196.0m, 35°
2019/02/08 13:22:23

PHOTO 5: GAS METER CALIBRATION LOG IS UP TO DATE