

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2019

Submitted Date:

02/09/2019

Document Number:

696100118**FIELD INSPECTION FORM**Loc ID 306532 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 289499 | WELL | PR | 09/01/2018 | OW | 123-24861 | ANDERSON 12-2 | PR |

General Comment:

This is a WELL Inspection.
 Centralized Battery serves 2 Location ID's (306531, 306532).
 Refer to FIR #696100115 and/or Location ID #306531 for Battery / Facility, Equipment info.
 Well is PR.

Location

| | | | |
|--------------------|----------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|--|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--|-------|--|
| Good Housekeeping: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Refer to FIR #696100115 and/or Location ID #306531 for additional Fencing info. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Other | # | | |
| Comment: | Refer to FIR #696100115 and/or Location ID #306531 for additional Equipment info. | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|----------|---|----------|------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|----------|---|----------|------|---------|--------|--|

| | | | | | |
|--------------------|--|---------------------|---------------------|-----------------------|--|
| | | CENTRALIZED BATTERY | | 40.521913,-104.754879 | |
| Comment: | Centralized Battery serves 2 Location ID's (306531, 306532). Refer to FIR #696100115 and/or Location ID #306531 for Tanks & Berms info. | | | | |
| Corrective Action: | | | | Date: | |
| Paint | | | | | |
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|--|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 289499 | Type: | WELL | API Number: | 123-24861 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Comment: | | Bradenhead appears plumbed to surface. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696100119 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729870 |