

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2019

Submitted Date:

02/11/2019

Document Number:

682504506**FIELD INSPECTION FORM**Loc ID 432936 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432937	WELL	PR	03/16/2015	OW	123-37367	FISCUS FEDERAL LD15-77HN	RI
432938	WELL	PR	03/16/2015	OW	123-37368	FISCUS FEDERAL LD15-76HN	RI
432940	WELL	PR	03/16/2015	OW	123-37369	FISCUS FEDERAL LD15-77-1HN	RI

General Comment:

[This is an interim reclamation and stormwater inspection. Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

Inspected Facilities			
Facility ID: 432937	Type: WELL	API Number: 123-37367	Status: PR Insp. Status: RI
Producing Well			
Comment:	PR Well, interim reclamation and stormwater inspection.		
Corrective Action:		Date:	
Facility ID: 432938	Type: WELL	API Number: 123-37368	Status: PR Insp. Status: RI
Producing Well			
Comment:	PR Well, interim reclamation and stormwater inspection.		
Corrective Action:		Date:	
Facility ID: 432940	Type: WELL	API Number: 123-37369	Status: PR Insp. Status: RI
Producing Well			
Comment:	PR Well, interim reclamation and stormwater inspection.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: Inspector mapped a disturbance area of 1.13 acres via a Trimble GPS unit. This DOES NOT appear to be in compliance with the approved Form 2A for the permitted disturbance area post interim reclamation (1 acres).

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Fail _____

Comment: Vehicle tracks evident leaving the pad from the north, south east and west ends into the interim areas. See photos #5-8

Corrective Action: Comply with 1002.e and restrict vehicles to the access road and pad.

Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment: No waste or debris found on location or reclamation area.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment: No unused/unneeded equipment/materials found being stored on location or reclamation area.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? <u>In</u>	Production areas stabilized ? <u>Pass</u>
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u>	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____
Perennial forage re-established _____	
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured _____
80% Revegetation _____	
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? _____	
Comment:	Operator does not appear to have saved topsoil (stored topsoil on the location) for future reclamation efforts. COGCC Staff recommends leaving enough topsoil stockpiled for final reclamation. Interim reclamation appears to be in process. Snow cover prevented an accurate assessment of reclamation and a follow-up inspection will need to be conducted in a future growing season to evaluate compliance with reclamation standards.
Corrective Action:	<div style="border: 1px solid black; height: 20px;"></div>
Date:	_____
Overall Interim Reclamation _____	
<u>Final Reclamation/ Abandoned Location:</u>	
Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: RANGELAND _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads Regraded _____	Contoured _____
Gravel removed _____	Culverts removed _____
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
Comment:	<div style="border: 1px solid black; height: 20px;"></div>

Inspector Name: Trujillo, Aaron

Corrective Action: <input style="width: 90%;" type="text"/>	Date: <input style="width: 90%;" type="text"/>					
Overall Final Reclamation <input style="width: 30%;" type="text"/> Well Release on Active Location <input style="width: 30%;" type="checkbox"/> Multi-Well Location <input style="width: 30%;" type="checkbox"/>						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>	<input style="width: 90%;" type="text"/>
Comment: <input style="width: 90%;" type="text" value="No issues observed."/>						
Corrective Action: <input style="width: 90%;" type="text"/>						Date: <input style="width: 90%;" type="text"/>
Pits: <input style="width: 10%;" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682504507	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4731061