

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2019

Submitted Date:

02/11/2019

Document Number:

689303215**FIELD INSPECTION FORM**

Loc ID 324044 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                              | Comment                         |
|--------------|-------|------------------------------------|---------------------------------|
| Rocky, TEP   |       | COGCCInspectionReports@terraep.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 211566      | WELL | PR     | 11/29/1998  | GW         | 045-07326 | CLOUGH RMV #208-20 | PR          |

**General Comment:**[Routine Field Inspection.](#)

### Location

**Lease Road:**

|                    |             |       |  |
|--------------------|-------------|-------|--|
|                    | Type Access |       |  |
| comment:           |             |       |  |
| Corrective ActionL |             | Date: |  |

Overall Good: ☒**Emergency Contact Number:**

|                    |                |       |  |
|--------------------|----------------|-------|--|
| Comment:           | 1-970-285-9377 |       |  |
| Corrective Action: |                | Date: |  |

**Good Housekeeping:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | DEBRIS |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |
| Type               | TRASH  |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |                  |       |  |
|--------------------|------------------|-------|--|
| Type               | WELLHEAD         |       |  |
| Comment:           | Panel gates.     |       |  |
| Corrective Action: |                  | Date: |  |
| Type               | SEPARATOR        |       |  |
| Comment:           | Hog panel fence. |       |  |
| Corrective Action: |                  | Date: |  |
| Type               | TANK BATTERY     |       |  |
| Comment:           | Hog panel fence. |       |  |
| Corrective Action: |                  | Date: |  |

**Equipment:**

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
|                                   |     |       | corrective date |
| Type: Plunger Lift                | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 3 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

|                       |     |       |
|-----------------------|-----|-------|
| Type: Bird Protectors | # 3 |       |
| Comment:              |     |       |
| Corrective Action:    |     | Date: |

**Tanks and Berms:**

|                    |   |           |           |         |        |
|--------------------|---|-----------|-----------|---------|--------|
| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 1 | <100 BBLS | STEEL AST |         | ,      |
| Comment:           |   |           |           |         |        |
| Corrective Action: |   |           |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |                                 |          |           |         |        |
|--------------------|---------------------------------|----------|-----------|---------|--------|
| Contents           | #                               | Capacity | Type      | Tank ID | SE GPS |
| CONDENSATE         | 1                               | 200 BBLS | STEEL AST |         | ,      |
| Comment:           | 2 tanks in centralized battery. |          |           |         |        |
| Corrective Action: |                                 |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|          |  |
|----------|--|
| Type     |  |
| Comment: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

| Inspected Facilities |                                 |       |      |             |           |         |    |               |    |
|----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 211566                          | Type: | WELL | API Number: | 045-07326 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                                 |       |      |             |           |         |    |               |    |
| Comment:             | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:   |                                 |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              |                       |               |                          |         |
| Seeding          |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                   | URL   |
|--------------|-------------------------------|---|
| 689303216    | Inspection photo<br>689303216 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4731259">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4731259</a> |