

**Reportable Release Photographic Documentation**

Dodd WTS (#3-2) – 1/5/2019: Source of spill originated from a broken bushing inside the pump building.



Dodd WTS (#3-2) – 1/5/2019: A new bushing was installed and the facility put back into service.

